## FORM D NONRESIDENTIAL LAND USE ASSESSMENT FOR FYNOP ANNUAL POST-REMEDIATION CARE PLAN ACTIVITIES

This form is used to document the results of annual post-remediation care activities for engineering and institutional controls at the Former York Naval Ordnance Plant (fYNOP) in York, Pennsylvania. These activities are to be performed in accordance with the procedures in the approved Pennsylvania Land Recycling and Environmental Remediation Standards Act (Act 2) Final Report and Post-Remediation Care Plan (PRCP) contained in Appendix J of the Final Report.

The activities covered by this form include reviewing low altitude aerial photographs using unmanned aircraft system (drone) technology and conducting a walk-over inspection to confirm nonresidential land use on the East and West Campus properties and in LUA 6 in accordance with Section 4.1.1 in the PRCP.

Which property and/or land use area (LUA) does this form cover?

<ul><li>✓ East Campus property and LUA 6.</li><li>✓ West Campus property.</li></ul>
Aerial Photograph Information
Date photographs taken: March 14, 2024 Company taking photographs: Hydro-Terra Group Equipment used: DJI Zenmuse XZ5S Camera & DJI Matrice 200 Drone Elevation of camera above ground surface: 50-200 feet Weather conditions: 61F, Sunny/Clear Skies, 1 mph wind from SW with 2 mph gusts Georeferencing Method: DJI Matrice 200 on-board GPS system Number of photographs taken: 1089 (East and West Campus)
Please include copies of the aerial photographs with this completed form. [One (1) summary/site aerial photograph provided only]
Did the aerial photograph review identify residential land use on the properties?  ✓ No.  ✓ Yes. If yes, describe the residential land use and identify the location(s) on a figure.
Did the aerial photograph review identify residential land use in LUA 6?  ☐ Not applicable. LUA 6 was not assessed.  ☑ No.
Yes. If yes, describe the residential land use and identify the location(s) on a figure.

## **Walk-Over Inspection Information**

Date of walk-over inspection: $\frac{3/14/2024}{4}$
Company performing the inspection: <u>Hydro-Terra Group</u>
Name of inspector: Emily Wade Weather conditions: Sunny, 60°F
Number of photographs taken:
Tunioer of photographs taken.
Please include copies of photographs taken during the inspection with this completed form.
Did the inspection identify residential land use on the properties?
☑ No.
Yes. If yes, describe the residential land use and identify the location(s) on a figure.
Did the inspection identify residential land use in LUA 6?
Not applicable. LUA 6 was not included in the walk-over inspection.
□ No.
Yes. If yes, describe the residential land use and identify the location(s) on a figure.
Other Observations
Were other noteworthy items related to annual post-remediation care activities identified during the nonresidential land use assessment?
✓ No.
Yes. If yes, describe the items.
Nonresidential Land Use Assessment Form Prepared By:
Hydro-Terra Group
Company Name
Rodney Myers, CHMM - Sr. Program Manager
Company Representative / Title
Roby Solyris 4/3/2025
Signature / Date
Consultant- fYNOP Team Member
Relationship to Owner of the Property















