

---

---

**SUPPLEMENTAL REMEDIAL INVESTIGATION  
GROUNDWATER REPORT (PART 2)  
Former York Naval Ordnance Plant  
1425 Eden Road  
York, PA 17402**

---

---

**Prepared for:**

**Former York Naval Ordnance Plant Remediation Team  
York, PA**

**August 2016  
Revised March 2018**

**Volume 2 of 4  
Tables**

**Prepared by:**

**Groundwater Sciences Corporation**

**2601 Market Place Street, Suite 310  
Harrisburg, Pennsylvania 17110**

**560 Route 52, Suite 202  
Beacon, New York 12508**

**1108 Vestal Parkway East, Suite 2  
Vestal, New York 13850**



## **Tables (Volume 2 of 4)**

Table 2.0-1	List of Addenda to the Field Sampling Plan
Table 2.1-1	Codorus Creek Flow Measurement Summary
Table 2.2-1	Well Information
Table 2.2-2	Groundwater Chemistry Data for Waterloo™ Wells
Table 2.2-3	Site-Wide Groundwater Levels and Elevation Data
Table 2.2-4a	Groundwater Data Summary – VOC Analysis
Table 2.2-4b	Groundwater Data Summary – SVOC Analysis
Table 2.2-4c	Groundwater Data Summary – Metals Analysis
Table 2.2-4d	Groundwater Data Summary – Other Analysis
Table 2.3-1a	Codorus Creek VOC Sample Results
Table 2.3-1b	Codorus Creek Metals Sample Results
Table 2.3-1c	Codorus Creek Other Sample Results
Table 2.3-2	Summary of Phase 3 Dye Injections – in text
Table 2.3-3	Monitored Natural Attenuation Sample Results
Table 2.3-4	2015 Comprehensive Sampling Program
Table 2.4-1	Water Sample Analysis Summary
Table 2.4-2	Quality Control Sample Analysis Summary
Table 2.4-3	Analytical Method Analysis Summary
Table 2.4-4	Water Sample Analysis Summary of Field Duplicates for Select VOCs
Table 2.4-5	Validated Results Summary
Table 2.4-6	Rejected Data Summary
Table 2.4-7	Statistics for Laboratory Non-Detect Data
Table 3.1-1	Summary of Initial Vertical Extent Drilling Results – in text

*August 2016/Revised March 2018*

Table 3.1-2	Vertical Gradient Data – in text
Table 3.1-3	Ratio of Feet of Voids per Feet of Bedrock Drilled in the Carbonate Formation Beneath the Site – in text
Table 3.1-4	Dye Sampling Results at SPBA and South of the Site
Table 3.3-1	Natural Attenuation Analytical and Field Screening Parameters
Table 3.3-2a	MNA Screening Process Calculations – Conduits in CPA
Table 3.3-2b	MNA Screening Process Calculations – Source/Plume in CPA
Table 3.3-2c	MNA Screening Process Calculations – Codorus Creek Levee
Table 3.3-2d	MNA Screening Process Calculations – NPBA
Table 3.3-2e	MNA Screening Process Calculations – SPBA
Table 3.3-2f	MNA Screening Process Calculations – WPL
Table 3.5-1	Creek Shut Down Monitoring Results for Station SW-16
Table 3.5-2	Creek Shut Down Monitoring Results for Station SW-27
Table 3.5-3	Creek Shut Down Monitoring Results for Station SW-13
Table 3.5-4	Creek Shut Down Monitoring Results for Station SW-28
Table 3.5-5	Creek Shut Down Monitoring Results for Station SW-8
Table 3.5-6	Creek Shut Down Monitoring Results for Station SW-9
Table 3.5-7	Creek Shut Down Monitoring Results for Station SW-29
Table 3.5-8	Creek Monitoring Results After System Restart for Station SW-16
Table 3.5-9	Creek Monitoring Results After System Restart for Station SW-27
Table 3.5-10	Creek Monitoring Results After System Restart for Station SW-13
Table 3.5-11	Creek Monitoring Results After System Restart for Station SW-28
Table 3.5-12	Creek Monitoring Results After System Restart for Station SW-8
Table 3.5-13	Creek Monitoring Results After System Restart for Station SW-9
Table 3.5-14	Creek Monitoring Results After System Restart for Station SW-29

Table 3.6-1	Dye Tracer Laboratory Results for Extraction Wells (water samples)
Table 3.7-1	Summary of GWRI Data Gaps Addressed in Part 2 – in text